

Inspection Photos  
Operator: Logos Operating  
API: 067-05594  
Date: 1/27/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, smooth brome, and sand dropseed.



Photo 3. View of southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of pinyon and juniper mixed with big sagebrush, James galleta, yucca, and Indian ricegrass.