

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402939619

Date Received:

01/27/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Lauren Morahan

720-644-6997

lmorahan@bisonog.com

Tarah Garza

970-692-1963

tgarza@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696303896

Inspection Date: 12/29/2021

FIR Submit Date: 12/29/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452871

Location Name: Castor 8-59 Number: 19 County: \_\_\_\_\_

Qtrqtr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.644946 Longitude: -104.011983

FACILITY - API Number: 05-123- -00 Facility ID: 452871

Facility Name: Castor 8-59 Number: 19

Qtrqtr: NESE Sec: 19 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.644946 Longitude: -104.011983

CORRECTIVE ACTIONS:

1 ☒ CA# 158948

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per 902.b.

Date: 01/31/2022

Response: CA COMPLETED

Date of Completion: 01/13/2022

Operator Comment: High winds and blowing debris damaged netting around the compressor day tank. Netting has since been repaired and reinstalled, see attached photo.

COGCC Decision: Approved

COGCC Representative: Approved

2 ☒ CA# 158949

Corrective Action: Install sign to comply with Rule 605.d.

Date: 01/31/2022

Response: CA COMPLETED

Date of Completion: 01/13/2022

Operator Comment: Castor Fed 8-59 19-24-3 well sign replaced. See attached photo.

COGCC Decision: Approved

COGCC Representative: Approved

4 ☒ CA# 158951

Corrective Action: Install sign to comply with Rule 605.h.

Date: 01/31/2022

Response: CA COMPLETED

Date of Completion: 01/26/2022

Operator Comment: Labels added to chemical totes. See attached photos

COGCC Decision: Approved

COGCC Representative: Approved

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lauren Morahan

Signed:

Title: Regulatory Manager

Date: 1/27/2022 3:49:41 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402939619	FIR RESOLUTION SUBMITTED
402939634	Castor 8-59 bird netting repair
402939641	Castor 8-59 19-24-3 well sign
402939645	Castor chem tote 1
402939647	Castor chem tote-2
402939650	Castor chem tote-3
402939652	Castor chem tote-4

Total Attach: 7 Files