

Inspection Photos  
Operator: Simcoe  
API: 067-06899  
Date: 1/31/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of northern fill slope from the northwestern corner facing eastward. Vegetation largely snow covered, and grazed at this time.



Photo 3. View of reference area comprised of open grass field with scattered pinyon, juniper and gambel oak trees.