

Inspection Photos
Location Name: Burr FD 23-219HN Pad
Location ID: 440510



Colorado Oil & Gas Conservation Commission
40.46713, -104.83312, 1423.9m, 9°
Jan 31, 2022 11:39:47 AM

Photo 1: Tank Battery Sign



Colorado Oil & Gas Conservation Commission
40.46726, -104.8332, 1430.3m, 82°
Jan 31, 2022 11:40:08 AM

Photo 2: Tank Battery

Inspection Photos
Location Name: Burr FD 23-219HN Pad
Location ID: 440510



Photo 3: Wellhead Sign



Photo 4: Stained soil

Inspection Photos
Location Name: Burr FD 23-219HN Pad
Location ID: 440510



Photo 5: Stained soil



Photo 6: Wellhead Sign

Inspection Photos
Location Name: Burr FD 23-219HN Pad
Location ID: 440510



Photo 7: Stained soil



Photo 8: Stained soil

Inspection Photos
Location Name: Burr FD 23-219HN Pad
Location ID: 440510



Photo 9: Missing bird protector