

Inspection Photos  
Location Name: Swanson 1-14  
Location ID: 321332



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Swanson 1-14  
Location ID: 321332




Photo 3 TB sign

Photo 4 TB

**Inspection Photos**  
**Location Name: Swanson 1-14**  
**Location ID: 321332**



Colorado Oil & Gas Conservation Commission  
 8646 N 119th St, Longmont, CO 80504, USA  
 40.13266, -105.07656, 4953.5ft, 41°  
 02/01/2022 11:09:19



100321425	716	161	Swanson #1-14	1412010910				
Radio #	Producer Name		Mtr Tube Size 2.0bt					
880-5489	EXTRACTUM OIL & GAS		County Boulder					
Transmitter / Module #	Federal #	State #	State CO					
1741541								
Static / Span / Up / Dwn	Diff / Span	Temp / Span	Absolute	API #				
900	UP	250	150°	12.2				
Test Date	OP Size	Beta	Sample Date	H:S	Sample Date	H:S	C'	Gravity
10-20-15	1.250		10-20-15	2.0				
3-25-16	1.250		3-25-16	2.5				
9-28-16	1.250		9-28-16	1.0				
3-10-17	1.250		3-10-17	1.5				
9-20-17	1.250		9-20-17	1.0				
3-27-18	1.250		3-27-18	3.0				
9-25-18	1.250		9-25-18	3.0				
3-21-19	1.250		3-21-19	2.0				
9-25-19	1.250		UPIA					
3-21-20	1.250		3-21-20	3.0				
3-27-21	1.25		LOT0					
9-27-21	1.25		LOT0					

Colorado Oil & Gas Conservation Commission  
 8646 N 119th St, Longmont, CO 80504, USA  
 40.1326, -105.07653, 4953.5ft, 36°  
 02/01/2022 11:09:34

**Photo 5 Gas Meter Run**

**Photo 6 Card indicates current calibration**

**Inspection Photos**  
**Location Name: Swanson 1-14**  
**Location ID: 321332**



**Photo 7 Horiz. Heated Sep.**