

Inspection Photos

API: 009-05157

Operator: PONCHO PRODUCTION COMPANY

Inspection Date: 2/1/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos



Photo 1. Facing southeast toward the location. There is a water well and stock tank at the location belonging to the landowner. The black two tanks shown were equipment from the well site which need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos



Photo 2. There are two tanks, pipe riser, meter run, and cement debris that remain. All equipment should have been removed within 3 months of well abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos



Photo 3. There are two tanks, pipe riser, and meter run that remain. All equipment should have been removed within 3 months of well abandonment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos




Photo 4. Facing southeast at the location. There are areas of the location with no vegetation growth which will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos



Photo 5. There is a yellow tank that remains at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos



Photo 6. Drone aerial photo facing southeast toward the abandoned well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022

Inspection Photos




Photo 7. Drone aerial photo facing north toward the abandoned well site. There are areas that have no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-05157 | Date: 2/1/2022