

Western Operating Company, Bobcat D Sand Unit 23

121-06551

Inspection #688312099

1/27/2022

Routine Field Inspection



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission  
40.02665, -103.59219, 188°  
01/27/2022 10:06:52 AM



Colorado Oil and Gas Conservation Commission  
39.97184, -103.66075, 4524.3ft, 4°  
01/27/2022 09:50:40 AM



Colorado Oil and Gas Conservation Commission  
39.97181, -103.66074, 4498.0ft, 16°  
01/27/2022 09:50:48 AM



Colorado Oil and Gas Conservation Commission  
39.97178, -103.66092, 4504.6ft, 40°  
01/27/2022 09:51:07 AM



Colorado Oil and Gas Conservation Commission  
39.97177, -103.66089, 4501.3ft, 294°  
01/27/2022 09:50:59 AM



Colorado Oil and Gas Conservation Commission  
39.97177, -103.66089, 4504.6ft, 228°  
01/27/2022 09:51:01 AM