


MARALEX RESOURCES INC
SOUTH SHALE RIDGE-68S98W 24SWNE
Location # 312609



EMS (911) not posted on battery sign.
Tank battery sign is illegible and does not meet Rule 605.e.

MARALEX RESOURCES INC
SOUTH SHALE RIDGE-68S98W 24SWNE
Location # 312609



Weeds around well, production equipment, and tank battery.



Tank label is illegible.

MARALEX RESOURCES INC
SOUTH SHALE RIDGE-68S98W 24SWNE
Location # 312609



Weeds around well, production equipment, and tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

MARALEX RESOURCES INC
SOUTH SHALE RIDGE-68S98W 24SWNE
Location # 312609



Weeds around well, production equipment, and tank battery.

MARALEX RESOURCES INC
SOUTH SHALE RIDGE-68S98W 24SWNE
Location # 312609



Access road is rutted and lacks stabilization. Road ditch needs maintained.

