

Inspection Photos
Location Name: Jillson 'A' #1
Spill ID: 478617 (CL)/ Remediation Project 18950



Photo 1 – Active spill at separator at Jillson A 1 Battery.

Photo 2 – Active spill at separator.

Inspection Photos
Location Name: Jillson 'A' #1
Spill ID: 478617 (CL)/ Remediation Project 18950




Photo 3 – Active spill at separator.



Photo 4 – Spill ID 478617 spill area.

Inspection Photos
Location Name: Jillson 'A' #1
Spill ID: 478617 (CL)/ Remediation Project 18950



Photo 5 – Pump shut off at wellhead.

Photo 6 – Hydrovac arrived at spill location. No gauge on hydrovac truck.

Inspection Photos
Location Name: Jillson 'A' #1
Spill ID: 478617 (CL)/ Remediation Project 18950



Photo 7 – Spill and current excavation extent

Photo 8 – Spill and current excavation extent