

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC TIPPING-67S96W /34NWNW**

**Location ID: 334094**



**Photo #5851 from entrance to location.**



**Photo #5852 from entrance to location.**

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC TIPPING-67S96W /34NWNW**

**Location ID: 334094**



**Photo #5853 No battery sign located at the tank battery.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources