

Inspection Photos  
Location Name: Loomis PAD  
Location ID: 438327



Photo 1 – Wellhead

Photo 2 – 2-6 Pumping Unit

**Inspection Photos**  
**Location Name: Loomis PAD**  
**Location ID: 438327**



**Photo 3 – 2-6H Engine**

**Photo 4 – 2-6H Exhaust**

**Inspection Photos**  
**Location Name: Loomis PAD**  
**Location ID: 438327**



**Photo 5 – 2-6H Wellhead**

**Photo 6 – 2-3H Exhaust and Engine**

Inspection Photos  
Location Name: Loomis PAD  
Location ID: 438327





Photo 7 – 2-3H Wellhead – Stained Soil

Photo 8 – 2-3H Wellhead – Stained Soil

Inspection Photos  
Location Name: Loomis PAD  
Location ID: 438327



Photo 9 – 2-1H Engine and Exhaust

Photo 10 – 2-1H Wellhead – Stained Soil

**Inspection Photos**  
**Location Name: Loomis PAD**  
**Location ID: 438327**



**Photo 11 – ECD and Flare**

**Photo 12 – Content and Capacity Labels updated**

Inspection Photos  
Location Name: Loomis PAD  
Location ID: 438327



Photo 13 – Tank Battery Signs

Photo 14 – Tank Battery

**Inspection Photos**  
**Location Name: Loomis PAD**  
**Location ID: 438327**



**Photo 15 – Heater Treaters and Gas Meters**