




# King Pyles #2 Soil Sample Locations

Western Operating Company  
Remediation Project # 20716  
November 9, 2021

## Legend

-  Approximate Area with Stressed Vegetation
-  King Pyles #2 Wellhead
-  Soil Sample Location

