

Dawson 1 Soil Sample Locations

Western Operating Company
Remediation Project # 20818
November 9, 2021

Legend

⦿ Soil Sample Location



Area with Stressed
Vegetation

SS4-1

SS1-1

Tilled Area

SS3-1

SS2-1

BG1-1