

Inspection Photos
Location Name: Hamill 19-16HA
Location ID: 442178



Photo 1. Overview of location taken facing southwest.



Photo 2. No bradenhead access apparent.



Inspection Photos
Location Name: Hamill 19-16HA
Location ID: 442178



Photo 3. Stained soil at pump jack exhaust.



Photo 4. Stained soil on location.