

Inspection Photos
Location Name: Harper Hill 1-29, 2-29
Location ID: 423735




Photo 1. Overview of location taken facing northwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Harper Hill 1-29, 2-29
Location ID: 423735



Photo 2. No bradenhead access apparent.



Photo 3. Both combustors lit.

