

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 1. Overview of location taken facing east.



Photo 2. Overview of location taken facing northeast.



Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 3. Tank labeled “out of service” remains on location.



Photo 4. Drip pot overflowing.

