

**Inspection Photos**  
**Location Name: Dwinell 3**  
**Location ID: 324592**



**Photo 1. Roads not maintained for winter.**

