

Inspection Photos

Operator: Kinder Morgan
API: 083-06634
Date: 2/7/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing southward. Vegetation remains sparse, similar to surrounding field. Some desirable species such as western wheatgrass and sand dropseed observed.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area comprised of open field with western wheatgrass, sand dropseed, and scattered weeds such as Russian thistle.