

Inspection Photos  
Operator: Kinder Morgan  
API: 083-06635  
Date: 2/7/2022



Photo 1. View of project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with western wheatgrass and sand dropseed observed in a grazed condition.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of open grass field and sagebrush shrubland mosaic with grasses such as western wheatgrass, Indian ricegrass, and sand dropseed.