

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NWNE

Location ID: 334716



Photo #5898 from entrance to location.



Photo #5899 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1NWNE

Location ID: 334716



Photo #5900 Location lacks stabilization.



Photo #5901 Insufficient tracking BMP at entrance to location.