

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5902 from entrance to location.



Photo #5903 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5904 Vent pipe on tank open ended.



Photo #5905 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT ET AL-66S96W /35SESE

Location ID: 334743



Photo #5906 Location lacks stabilization.



Photo #5907 Insufficient tracking BMP located at entrance to location.