

Rory 1

Photographic Log

Remediation #20088


Wellhead and Flowline Decommissioning



EAGLE
ENVIRONMENTAL
CONSULTING, INC.

8000 W 44th Ave, Wheat Ridge, CO 80033
Ph: 303-433-0479 • F: 303-325-5449

Wellhead and Flowline



Wellhead Sample Location
PID = photoionization detector
Ppm-v = parts per million by volume



Flowline Riser Sample Location

Wellhead and Flowline



Wellhead North



Wellhead East

Wellhead and Flowline



Wellhead South



Wellhead West

Wellhead and Flowline



Flowline 1



Flowline 2