

Inspection Photos
Location Name: Ballentine 4-30A
Location ID: 331484



Photo 1 Crew cleaning out the tracking pad and leveling out the entrance to location



Photo 2 Dirt and mud being tracked off location south bound on County Line Rd.

Inspection Photos
Location Name: Ballentine 4-30A
Location ID: 331484



Photo 3 Dirt and mud being tracked off location North on County Line RD.



Photo 4 Dirt and mud being tracked off location South on County Line RD.

Inspection Photos
Location Name: Ballentine 4-30A
Location ID: 331484



Photo 5 Tracking pad being reset after cleaning.



Photo 6 Tracking pad being reset after cleaning.

Inspection Photos
Location Name: Ballentine 4-30A
Location ID: 331484



Photo 7 Access through TB location wet and muddy.

Photo 8 Access Rd. Muddy with deep ruts.

Inspection Photos
Location Name: Ballentine 4-30A
Location ID: 331484



Photo 9 Access Rd. muddy with deep ruts entering location.

Photo 10 Access Rd. Muddy with deep ruts leaving location.

Inspection Photos
Location Name: Ballentine 4-30A
Location ID: 331484



Photo 11 Ensign Workover Rig, muddy location.

Photo 12 Cleaned tracking pads leaving location.