

Inspection Photos
Operator Name: Maralex Resources INC.
Location ID: 312424



Wellhead marker welded onto casing ,
4' below grade



Gas meter, Building and riser will need to be
removed before final reclamation can be passed

Inspection Photos
Operator Name: Maralex Resources INC.
Location ID: 312424



Location photo, No debris on location



On-locations 2" flowlines dug up and removed