

Inspection Photos
Operator Name: Maralex Resources INC.
Location ID: 312365



Location photo, No debris on location

Inspection Photos
Operator Name: Maralex Resources INC.
Location ID: 312365



**Gas gathering marker on edge of location
no visual sign of riser**



**Flowlines were abandoned, dug up and
removed from location**