

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Colorado Oil and Gas Conservation Commission
40.59483, -104.29932, 4876.7ft, 290°
02/10/2022 11:23:07



Colorado Oil and Gas Conservation Commission
40.5947, -104.2994, 4894.6ft, 63°
02/10/2022 11:22:40

Photo 1 – Gas Lines – Going to Sales and ECD

Photo 2 – Gas Sales Line LOTO

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875




Photo 3 – Gas Line Valve Shut




Photo 4 – Gas Sales – LOTO

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875




Photo 5 – Valves Closed at Gas Meter going to ECD

Photo 6 – Valve Open going to ECD

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 7 – Wellhead

Photo 8 – Wellhead Sign

Inspection Photos
Location Name: Perrin 1-10H
Location ID: 424875



Photo 9 – ECD

Photo 10 – Valve to Gas Sales – LOTO, Gas to ECD Open