

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2022

Submitted Date:

02/11/2022

Document Number:

699602704

FIELD INSPECTION FORMLoc ID 481574 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481573	TANK BATTERY	AC	02/09/2022		-	SESE 29-6N-64W Miller Tank Battery	IO

General Comment:

This is a TANK BATTERY inspection.
Battery: Inactive. Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID
(481573).
Centralized Battery serves 1 Location ID
(323297).
(Well(s): 1: Shut-In | SI).

-Refer to Field Inspection Report doc. #699602706 and/or Location ID #323297 for Well(s) info.
Well(s): 1: Shut-In | SI.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by earth berms.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas Sales. Calibration card indicates calibration within last year. Last calibration: 05/04/2021. Inactive, no production.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (481573). Centralized Battery serves 1 Location ID (323297).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	48 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares berms w/ crude oil tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.449932,-104.566333
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: Shares bems w/ produced H2O vault.					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 01/28/2022 at approximately 15:26 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Facility Name: SESE 29-6N-64W Miller Tank Battery / Facility ID: 481573 Well Name(s): Miller 16-29. API: 05-123-12830. Location County: Weld County, Colorado Weather: Mostly Sunny, partial snow coverage from prior storm.</p> <p>While there, I observed: Battery: Inactive. Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481573). Centralized Battery serves 1 Location ID (323297). (Well(s): 1: Shut-In SI).</p> <p>-Refer to Field Inspection Report doc. #699602706 and/or Location ID #323297 for Well(s) info. Well(s): 1: Shut-In SI.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/11/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602705	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662481