

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 1 – Wellhead




Photo 2 – Unused Wellhead Parts

Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 3 – Separators



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 5 – Signage now posted



Photo 6 – Capacity now posted



Inspection Photos
Location Name: Washburn GX 15-62HN
Location ID: 428699



Photo 7 – Tank Battery