

Inspection Photos
Location Name: MILLER-66N64W /29NWSE
Location #: 330698




Photo #1
Miller 33-29 (05-123-19479) Wellsite
Temporarily Abandoned | TA



Photo #2
Miller 33, 43-29 Tank Battery /
Battery site
Inactive / Shut-down
Equipment documented Fac. ID 481572