

Inspection Photos
Location Name: Rabbit Ears O681 23 Location ID 449274



Location 449274.



Staining down metal containment wall and on snow.

Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



Northern load valve spill containment full of frozen produced water.



Southern most load valve spill containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



Tank battery secondary containment with drifted snow.



Tank battery secondary containment with drifted snow.

Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



API Well 057-06598



Well sign.



Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



API 057-06598



View looking east at tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources