

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



Photo #5918 from entrance to location.



Photo #5919 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



**Photo #5920 Vent pipe on tank open ended.**



**Photo #5921 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



**Photo #4893 from inspection #699803619 conducted on 9/15/21.**



**Photo #5922 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



**Photo #4895 from inspection #699803619 conducted on 9/15/21.**



**Photo #5925 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2NWNE

Location ID: 323884



**Photo #5923 Insufficient tracking BMP located at entrance to location.**