

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESE

Location ID: 335356



Photo #5944 from entrance to location.



Photo #5945 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /28SESE

Location ID: 335356



Photo #5946 Location lacks stabilization.



Photo #5947 Insufficient tracking BMP located at entrance to location.