

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2022

Submitted Date:

02/14/2022

Document Number:

699602736**FIELD INSPECTION FORM**Loc ID 302881 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413281	WELL	TA	12/01/2019	OW	123-30639	70 RANCH USX BB 09-99HZ	TA

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Temporarily Abandoned | TA.  
Battery: Inactive. Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID (481582).  
Centralized Battery serves 1 Location ID (302881).  
(Well(s): 1: Temporarily Abandoned | TA)  
Centralized Battery formerly served 1 Location ID / API# (302881 / 05-123-29970).  
(Well(s):1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #699602734 and/or Facility ID #481582 for Battery / Facility, Equipment info.

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.420028,-104.444201

Comment:	Centralized Battery serves 1 Tank Battery Facility ID (481582). Centralized Battery serves 1 Location ID (302881). (Well(s): 1: Temporarily Abandoned   TA) Centralized Battery formerly served 1 Location ID / API# (302881 / 05-123-29970). (Well(s):1: Plugged & Abandoned   PA).  Refer to Field Inspection Report doc. #699602734 and/or Facility ID #481582 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

**Paint**

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 413281 Type: WELL API Number: 123-30639 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Disconnected from flowline.  
COGCC records last production: 06/2018.

Form 4 Sundry on file. TA date: 08/14/2018.  
Approved.  
Form 21 MIT on file. MIT date: 09/02/2019.  
Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 02/09/2022 at approximately 16:54 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: 70 RANCH USX BB /09-99HZ  Location ID: 302881  Well Name(s):  70 Ranch USX BB 09-99HZ.  API: 05-123-30639.  Location County: Weld County, Colorado  Weather: Partly Sunny, partial snow coverage from prior storm.</p> <p>While there, I observed:  Well(s): 1: Temporarily Abandoned   TA.  Battery: Inactive. Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481582).  Centralized Battery serves 1 Location ID (302881).  (Well(s): 1: Temporarily Abandoned   TA)  Centralized Battery formerly served 1 Location ID / API# (302881 / 05-123-29970).  (Well(s):1: Plugged &amp; Abandoned   PA).</p> <p>Refer to Field Inspection Report doc. #699602734 and/or Facility ID #481582 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/14/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602737	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664292">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664292</a>