

Inspection Photos
Operator: Simcoe
API: 067-07878
Date: 2/11/2022



Photo 1. View of project area from the northwestern corner of the working area facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of pinyon and juniper/sagebrush shrubland mosaic with Indian ricegrass, squirreltail, blue grama, and snakeweed in the understory.