

Inspection Photos
Operator: Catamount Energy
API: 067-09073
Date: 2/11/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of mosaic of open grass field with smooth brome, crested wheatgrass, and western wheatgrass, and pinyon and juniper woodland with Indian ricegrass, squirreltail, blue grama, and snakeweed in the understory.