

Inspection Photos

API: 017-07298

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 2/10/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07298 | Date: 2/10/2022

Inspection Photos




Photo 1. Drone photo facing north at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07298 | Date: 2/10/2022

Inspection Photos



Photo 2. Drone photo facing south at the center of the location.



Inspection Photos



Photo 3. Drone photo facing east at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07298 | Date: 2/10/2022

Inspection Photos



Photo 4. Drone photo facing west at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07298 | Date: 2/10/2022

Inspection Photos



Photo 5. View of groundcover at the location shows desirable vegetation cover consisting of Sand drop seed, Blue grama, Sideoats among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07298 | Date: 2/10/2022