

Inspection Photos

API: 017-06431

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 2/10/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-06431 | Date: 2/10/2022

Inspection Photos



Photo 1. Drone aerial photo facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06431 | Date: 2/10/2022

Inspection Photos



Photo 2. Facing down toward the location. There was recent reclamation performed at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06431 | Date: 2/10/2022

Inspection Photos




Photo 3. Drone aerial photo facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06431 | Date: 2/10/2022