

# Inspection Photos

API: 017-06887

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/10/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 017-06887 | Date: 2/10/2022

## Inspection Photos



**Photo 1.** Facing north toward the former access road. There are areas along the road that have not established desirable vegetation and could benefit from additional reseeding.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06887 | Date: 2/10/2022



## Inspection Photos



**Photo 2.** Drone aerial photo facing north toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06887 | Date: 2/10/2022



## Inspection Photos



**Photo 3.** Facing down north toward the location. Most of the location consists of undesirable weeds (Kochia). The location will need to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06887 | Date: 2/10/2022



## Inspection Photos



**Photo 4.** Facing southeast toward the location. Most of the location consists of undesirable weeds (Kochia). The location will need to be reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06887 | Date: 2/10/2022