

Inspection Photos

API: 017-06918

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/10/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-06918 | Date: 2/10/2022

Inspection Photos



Photo 1. Facing northwest toward the access road. The access road was pre-existing and does not need to be reclaimed. The posts installed along the road need to be removed and any disturbance from removal reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06918 | Date: 2/10/2022

Inspection Photos



Photo 2. Facing west toward the location. The desirable vegetation is not establishing and the location will need to be reseeded. The posts around the location need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06918 | Date: 2/10/2022

Inspection Photos



Photo 3. Facing southeast toward the location. Areas of location will need to be reseeded. The posts around the location need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06918 | Date: 2/10/2022

Inspection Photos



Photo 4. Facing northwest toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06918 | Date: 2/10/2022