

# Inspection Photos

API: 073-06414

Operator: VECTA OIL & GAS

Inspection Date: 2/10/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022

## Inspection Photos



**Photo 1.** Drone aerial image facing southeast toward the former access road. There are areas along the road that have not established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022



## Inspection Photos



**Photo 2.** Drone aerial image facing southeast toward the former access road. There are areas along the road that have not established vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022



## Inspection Photos



**Photo 3.** Drone aerial photo facing north toward the location. The brown vegetation color at the location is undesirable weeds (Kochia).




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022



## Inspection Photos



**Photo 4.** Facing down north at the location. Most of the location consists of undesirable weeds (Kochia). The location will need to be reseeded and weeds need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022



## Inspection Photos



**Photo 5.** Facing down toward the location. Most of the location consists of undesirable weeds (Kochia). The location will need to be reseeded and weeds need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022



## Inspection Photos



**Photo 6.** Facing east at the location. Most of the location consists of undesirable weeds (Kochia). The location will need to be reseeded.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022



## Inspection Photos



**Photo 7.** Facing east toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06414 | Date: 2/10/2022