

# Inspection Photos

API: 073-06129

Operator: CITATION OIL & GAS CORP

Inspection Date: 2/11/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06129 | Date: 2/11/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing southwest toward the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06129 | Date: 2/11/2022

## Inspection Photos



**Photo 2.** Drone aerial photo facing southwest along flowline area adjacent to the access road. It appears there was an impacted area along the flowline where vegetation is impacted.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06129 | Date: 2/11/2022

## Inspection Photos



**Photo 3.** Drone aerial photo facing southwest toward the fenced location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06129 | Date: 2/11/2022

## Inspection Photos



**Photo 4.** Drone aerial photo facing northeast toward the fenced location. The brown vegetation color at the location is undesirable weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06129 | Date: 2/11/2022

## Inspection Photos



**Photo 5.** Facing northeast toward the location. It appears the weeds at the location had been mowed since previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06129 | Date: 2/11/2022