

Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326




Tank battery Sign.



Hose stored in tank battery.

Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326



Load out valve secondary containment overflowing.

Load out procedure sign.



Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326



Tank labeling illegible.

Tank labeling illegible.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326



Oil impact material (E&P waste) from Spill ID 473059
discovered on 03/09/2020.



Trash/debris.



Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326



Trash/Debris.



500 bbl crude Tank #10N79K23 staining on the ground at load valve and coupling.

Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326



Oil impact material (E&P waste) from Spill ID 473059 discovered on 03/09/2020 and trash/debris.



Chemical tote "Paraffin Solvent" in lined secondary containment. Note: 6" to 8" hole in secondary containment.

Inspection Photos February 10, 2022

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326



Pit facility ID: 115273 covered with snow.

Dwinell #1 well.

