

Inspection Photos
Location Name: Judy 4N64W6W
Facility ID: 481585



Photo #1 Tank battery



Photo #2 Production Equipment

Inspection Photos
Location Name: Judy 4N64W6W Tank Battery
Facility ID: 481585



Photo #3 Unused Equipment



Photo #4 Missing Netting