

Inspection Photos  
Location Name: Duckworth 32-16  
Location ID: 336107



Photo 1 WH sign



Photo 2 WH



Inspection Photos  
Location Name: Duckworth 32-16  
Location ID: 336107



Photo 3 WH sign



Photo 4 WH

Inspection Photos  
Location Name: Duckworth 32-16  
Location ID: 336107



Photo 5 TB sign




Photo 6 TB



# Inspection Photos Location Name: Duckworth 32-16 Location ID: 336107



Colorado Oil & Gas Conservation Commission  
 9829 Shoreline Dr, Longmont, CO 80504, USA  
 40.14193, -105.00292, 4822.2ft, 205  
 02/16/2022 12:55:09



Colorado Oil & Gas Conservation Commission  
 9829 Shoreline Dr, Longmont, CO 80504, USA  
 40.14189, -105.00295, 4819.6ft, 57  
 02/16/2022 12:55:32

Photo 7 Gas Meter Run

Photo 8 Card indicates current calibration

**Inspection Photos**  
**Location Name: Duckworth 32-16**  
**Location ID: 336107**



**Photo 9 ECD and Horiz. Heated Separator**