

Inspection Photos  
Operator: Arkoma  
API: 067-05377  
Date: 2/15/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass. Russian thistle debris needs to be removed and properly disposed of.





Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View of reference area vegetation comprised of pinyon and juniper woodland, with sagebrush, blue grama, Indian ricegrass, and yucca observed in the understory.