

# Inspection Photos

API: 041-06065

Operator: ULTRA RESOURCES INC

Inspection Date: 2/11/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022

## Inspection Photos



**Photo 1.** Facing south at the beginning of the access road. There is a wire gate not shown in the photo that requires maintenance. Lat/Long:38.75165,-104.55224.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 2.** There is an erosion channel long the road at LatLong:38.74925,-104.55225. This area needs to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 3.** There is a rock check dam at this point which needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 4.** There is a rock check dam at this point which needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 5.** Facing south along the access road. The remainder of the road is stabilized..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 6.** Facing southwest along the reclaimed portion of the road. The vegetation is progressing to 80% of reference area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 7.** Facing south at the reclaimed location. The vegetation is progressing to 80% of reference area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022



## Inspection Photos



**Photo 8.** Facing north at the reclaimed location. The vegetation is progressing to 80% of reference area levels.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 041-06065 | Date: 2/11/2022