

Final Reclamation Inspection

February 14, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 416310

Inspection Document #: 697503714

Weld County, CO

NENE Section 32 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: AG Multi Well Pad Section 32

Location ID: 416310



Photo 1. Photo taken from the associated offsite tank battery, facing East. Photo illustrates Operator has performed final reclamation activities with the evidence of drill rows.



Photo 2. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 1.

Inspection Photos
Location Name: AG Multi Well Pad Section 32
Location ID: 416310



Photo 3. Photo taken from the well location, facing Northwest. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing West. See comments under Photo 1.