

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SESW

Location ID: 334869



Photo #5966 from entrance to location.



Photo #5968 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /2SESW

Location ID: 334869



**Photo #5967** Location lacks stabilization.



**Photo #5969** Insufficient tracking controls at entrance to location.