

# Final Reclamation Inspection

February 14, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 332974

Inspection Document #: 697503724

Weld County, CO

NWSW Section 4 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DUKE USX J-65N66W /4NWSW  
Location ID: 332974



**Photo 1.** Photo taken from the western location, facing East. Photo illustrates Operator has removed all equipment from location and left the location rough for subsequent final reclamation.

Inspection Photos  
Location Name: DUKE USX J-65N66W /4NWSW  
Location ID: 332974



**Photo 2.** Photo taken from the western location, facing Northeast. See comments under Photo 1.