

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0797-05-52 Pad

Location ID: 334774



Photo #5977 from entrance to location.



Photo #5978 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0797-05-52 Pad

Location ID: 334774



Photo #5979 Location lacks stabilization.



Photo #5980 Location lacks stabilization.

Inspection Photos

Location Name: LARAMIE ENERGY LLC CC /0797-05-52 Pad

Location ID: 334774




Photo #5982 Insufficient tracking BMP located at entrance to location.